

IMPORTANT SAFETY RECALL NOTICE

VOLUNTARY RECALL OF RYOBI 40 VOLT BRUSHLESS 21" CORDLESS WALK-BEHIND MOWERS

Sold at Home Depot from February 2021 through January 2025



Location of Model Number and Serial Number

Model Numbers

RY401014BTLUS, RY401014US, RY401140US, RY401015BTLUS, RY401015US, RY401150US, RY401140US-Y, RY401150US-Y, RY401160US, and RY401016US

Serial Numbers

KC21032D010001 - KC21327N999999

A push-on connector inside the powerhead can overheat, posing a fire hazard.

Consumers should immediately discontinue use of the product and contact Ryobi Customer Service for instructions on how to disable the recalled mower and receive a free replacement 21" walk-behind mower.

If you have any questions or require additional information, please contact Ryobi Customer Service at [1-800-597-9624](tel:1-800-597-9624) from 9 a.m. to 5 p.m. ET or visit www.ryobitools.com.